


EXPLANATION:

- MW-2** ● MONITORING WELL
 [---] JUNE-JULY 2002 EXCAVATION LIMITS

- Notes: 1. The locations of all features shown are approximate.
 2. Onsite facilities were demolished in June 2002, with the exception of the existing building located at the south end of the site.
 3. This figure is for informational purposes only. It is intended to assist in the identification of features discussed in a related document. Data were compiled from sources as listed in this figure. The data sources do not guarantee these data are accurate or complete. There may have been updates to the data since the publication of this figure. This figure is a copy of a master document. The master hard copy is stored by GeoEngineers, Inc. and will serve as the official document of record.
- Reference: Drawing entitled "Temporary Erosion and Sediment Control Plan with Demolition Notes, Northwest Maritime Center, Demolition & Remediation Work" Port Townsend, WA" dated 03/19/02.



GeoEngineers

SITE PLAN

FIGURE 2